



M



the
perfect
couple



MX

M 3400	M 4600	M 5800	M 7200
1020-3400 L/h	1380-4600 L/h	1740-5800 L/h	2160-7200 L/h
3,5 - 5 W	3,7 - 8 W	3,8 - 10 W	4,3 - 15 W

220 - 230 V ~ 50 Hz
Flow rate
Power absorbed

MX 9800	MX 11600	MX 13400	MX 15200
2940-9800 L/h	3480-11600 L/h	4020-13400 L/h	4560-15200 L/h
4,4 - 16 W	4,5 - 18 W	6,1 - 20 W	6,2 - 24 W

M 900	M 1200	M 1500	M 1900
270-900 gph	360-1200 gph	450-1500 gph	570-1900 gph
1.5 - 6 W	1.7 - 9 W	2.3 - 14 W	2.4 - 15 W

120 V ~ 60 Hz
Flow rate
Power absorbed

MX 2600	MX 3000	MX 3500	MX 4100
780-2600 gph	900-3000 gph	1050-3500 gph	1230-4100 gph
2.5 - 17 W	3.3 - 19 W	3.9 - 22 W	5.9 - 29 W